From:

Ex. 6 PP / Ex. 7(C)

Sent:

11/16/2018 5:34:34 PM

To:

COLLINS Jay [Jay.COLLINS@state.or.us]

Subject:

RE: POR005 - SoloPower

Hi Jay,

Just touching base again. Any chance Ex. 6 PP / Ex. 7(C) has provided you with a complete waste inventory yet? Are they still configuring what was left inside the building? Has anything been removed for disposal? Thanks Ex. 6 PP / Ex. 7(C)

Ex. 6 PP / Ex. 7(C) Special Agent U.S. EPA R10 805 SW Broadway Portland OR 97205

Ex. 6 PP / Ex. 7(C)



WARNING - THE INFORMATION CONTAINED HEREIN MAY INCLUDE LAW ENFORCEMENT SENSITIVE AND/OR PRIVACY ACT INFORMATION, THE FURTHER DISTRIBUTION OF WHICH (BEYOND THE RECIPIENTS TO WHOM IT HAS BEEN ADDRESSED) MAY BE IN VIOLATION OF FEDERAL INFORMATION SECURITY REGULATIONS, CIVIL AND/OR CRIMINAL LAW WITHOUT THE EXPRESSED PRIOR WRITTEN CONSENT TO RELEASE AND/OR DISSEMINATE FURTHER BY THE U.S. EPA-CID. IF YOU ARE NOT THE INTENDED RECIPIENT PLEASE CONTACT THE SENDER BY REPLY E-MAIL AND DESTROY ALL COPIES OF THE ORIGINAL MESSAGE AND ATTACHMENTS.

From: COLLINS Jay <Jay.COLLINS@state.or.us>

Sent: Monday, October 15, 2018 2:16 PM

To Ex. 6 PP / Ex. 7(C)

Subject: FW: POR005 - SoloPower

Ex. 6 PP / Ex. 7(C)

DEQ Annual Report Coordinator Mary Fritzmann started this email chain showing the consultant for the property owner's contact with DEQ which started the work on this abandoned waste situation.

Ex. 6 PP / Ex. 7(C) s contact info is below, also.

Let me know if you need more.

Jay

Jay Collins Hazardous Waste Inspector/Project Manager Oregon DEQ Northwest Region 700 Lloyd Building Ex. 6 PP / Ex. 7(C)

Mary,

| From: FRITZIVIAININ IVIARY Sent: Moderandor: Sentember 05, 2019 7:42 AM |
|--|
| Sent: Wednesday, September 05, 2018 7:42 AM To: ORDIFN Audrous Obstan Audrous Obstan state on the COLUMN Investor COLUMN Investor Columns Inv |
| To: OBRIEN Audrey < Obrien. Audrey@deq.state.or.us >; COLLINS Jay < COLLINS. Jay@deq.state.or.us > |
| Subject: FW: POR005 - SoloPower |
| 316 Audrey and Jay |
| Hi Audrey and Jay, |
| |
| Ex. 6 PP / Ex. 7(C) called yesterday regarding the SoloPower cleanout. |
| [Ex. 6 PP / Ex. 7(C)] contract with SoloPower expired and the landowner may contract with uring the cleanout. |
| Ex. 6 PP / Ex. 7(C) is active in the cleanout. |
| Ex. 6 PP / Ex. 7(C) is active in the cleanout. |
| The county is in charge of the property for now. They placed a lien on it and plan to auction the equipment in the |
| building. The county contacts are Carlos Rouse(sp?) and Jeff Brown. |
| building. The country contacts are carlos rouse(sp:) and sen brown. |
| The landowner hired TetraTech and they have been doing quarterly 'check-ins' at the site over the years. |
| The landowner filled red a fech and they have been doing quarterly check-ins at the site over the years. |
| Stacey can provide access to the site. Not sure when the cleanout contract will be in place. |
| Stacey can provide access to the site. Not sure when the cleanout contract will be in place. |
| Feel free to contact [5.09/5.70]. I told [5.7] I would forward — email to NWR. |
| reel free to contact [amaza] I told [] would forward]email to ivvv. |
| 8 days c |
| Mary |
| Mary Fritzmann |
| Oregon DEQ Hazardous Waste Policy and Program Development |
| Ex. 6 PP / Ex. 7(C) |
| |
| From: Ex. 6 PP / Ex. 7(C) |
| From: Ex. 6 PP / Ex. 7(C) Sent: Tuesday, September 4, 2018 2:01 PM |
| |
| To: FRITZMANN Mary <fritzmann.mary@deq.state.or.us> Cc: Ex. 6 PP / Ex. 7(C)</fritzmann.mary@deq.state.or.us> |
| |
| Subject: POR005 - SoloPower |

I got your information from the Property Owner's (LIT Industrial, LP) Property Manager (Colliers). Environmental Asset Services, Inc. (EASI) is the Property Owner's environmental risk manager. We will be involved with the County and other interested parties to see that the hazardous materials and/or hazardous wastes are appropriately disposed and/or recycled. Please note that the building has been rekeyed, and access is controlled by **Ex. 6 PP / Ex. 7(C)**

The 2017 Annual Report activity was last reported as of 2/6/2018 by SoloPower, which has the responsibility to be in compliance by reporting and disposing hazardous waste before withdrawing the active RCRA Waste ID Number (which stays with the property, not the company). Please note that we are working towards maintaining SoloPower as the RP.

| | *************************************** |
|--|---|
| DCD LCC ID ODO00000450 C.I.D. C. | * |
| RCRA Site ID: ORO000030450 SoloPower Systems | $m\alpha$ |
| rectal bite ib. Gregovoso is o | |
| COOK ASSESSED TO THE | * *** |
| 6308 N. MARINE DRI | V H |
| obooti, in that bid | |
| 500mt 11m 05 0m | |
| PORTLAND. OR 972 | 21123 |
| TORTEMID, OR 7/2 | ~~~; |

IF, we are unable to maintain SoloPower as the RP, we will request a RCRA Waste Site ID Form to show an ownership change, which we understand would be at no charge. We understand that we would then be responsible for the one-time disposal activity on the 2018 Annual Report as well as the associated fees. We would then request in writing to have the RCRA Waste ID Number withdrawn on the Annual Report after the removal activity was completed. Should our future Tenant need to dispose of Hazardous Wastes, we will assist them to getting their information set up in your system.

Should you have any further questions please don't hesitate to reach out to me directly.

Ex. 6 PP / Ex. 7(C)

Environmental Asset Services, Inc.

3501 Jamboree Road, Suite 230 | Newport Beach, CA 92660

Ex. 6 PP / Ex. 7(C)

Please consider the environment before printing this email

This message and any attachments may be privileged, confidential or proprietary, if you are not the intended recipient of this email or believe that you have received this correspondence in error, please contact the sender through the information provided above and permanently delete this message.